



Time Check Park







Section One


*Flood Stage is 12 ft. above NOAA's NAVD88 Datum Water Line of 710.4 ft. Recent Water Level of the Cedar River (shown as "0" at right of sections) is observed to be ~4 ft. Above NAVD88 Line.







*This concept represents an illustrative vision of the Greenway Parks and does not represent final designs or specifications.


Amenities, features, and roads may be altered through future design and implementation of the Flood Control System.





^{*}This concept represents an illustrative vision of the Greenway Parks and does not represent final designs or specifications. Amenities, features, and roads may be altered through future design and implementation of the Flood Control System.






Riverfront Park



Riverfront Park: Precedent Images





Section Five

*This concept represents an illustrative vision of the Greenway Parks and does not represent final designs or specifications.

Amenities, features, and roads may be altered through future design and implementation of the Flood Control System.



Czech Village Park




Czech Village Park: Precedent Images



Czech Village Park: Precedent Images



Czech Village Park: Precedent Images



Czech Village Park: Paha Gardens

